



Fig. 5



$$\theta = \frac{9.2}{9.5} = 75^\circ$$

$$\therefore \text{lean} = 15^\circ$$


Fig. 2



$$\theta = \sin^{-1} \frac{7.4}{7.6} = 76^\circ$$

$$\therefore \text{lean} = 14^\circ$$

Fig. 9




$$\theta = \sin^{-1} \frac{9.0}{9.2}$$

$$= 76^\circ$$

$$\therefore \text{lean} = 12^\circ$$

Fig. 12



$$\theta = \sin^{-1} \frac{9.0}{9.3} = 75^\circ$$

$$\therefore \text{lean} = 15^\circ$$





FIG. 3.



11 conversion

$$\tan^{-1}\left(\frac{2.0}{4.5}\right) = 24.0$$


$$\frac{5.1}{2.0}$$

$$\theta = \sin^{-1} \frac{4.6}{5.1} = \sin^{-1} 0.90$$

$$= 65^\circ$$

$$\therefore \text{lean} = 25^\circ$$

FIG. 5.



$$\tan^{-1}\left(\frac{2.1}{4.9}\right) = 23.2$$

$$\theta = \sin^{-1} \frac{4.9}{5.1} = 0.9074674$$

$$= 65^\circ$$

$$\therefore \text{lean} = 25^\circ$$

4,921,252

FIG. 3




FIG. 14A




FIG. 14B

